Serial No.: 10/574,102 Amendment dated July 5, 2007

Reply to Office Action on April 5, 2007

Docket No.: 66722-086-7

IN THE SPECIFICATION:

Page 3, lines 6-7, replace the brief description of drawings with the

following amended description.

Fig. 4 is a side view of the printed circuit board with the microphone

associated therewith. therewith, and

Page 3, line 27 to page 4, line 2, replace the paragraph with the following

amended paragraph.

The upper shell part 3 comprises a battery drawer part 31 and has sound

inlet openings 32 at both sides for allowing sound to reach the further

microphone 13. The sound inlet openings 32 in the tops top shell part 3

corresponds with the sound inlets 14 when the top and bottom shell parts

are assembled. Also, the top shell part 3 has a further sound inlet

opening 33 32 for guiding sound into the sound canal 42 leading to the

microphone 4. As seen in fig. 2, the sound opening 32 has a snout part

33 which is open towards the inside of the hearing aid. This snout part is

dimensioned to receive the mouth of the sound canal 42 when the top

shell 3 is placed over the circuit board 2 in order to assemble the top and

bottom parts of the hearing aid.

-2-